



3rd cell from the input coupler, showing position of thermometer assembly with respect to end assemblies, see next...





On cell 7 itself:

Green line shows the approximate location of engraving tool mark.

It is on the cell-side, right at the edge of the weld-prep